DART AEROSPACE LTD	Work Order :	19952
	Description:	Inspection
		$\Omega$
	Approval :	
		Page 1 of 1

Step	Location	Procedure ,	Ву	Date
1	PK	Remove from Stock Yes/No Return# 287  Qty Part Number Description Batch  3 V10007 Part Number B 18956	1	03.11.11
2	DIL as	Re-work/Inspection:  Departage as per PIP 1/400007  return to stack		04-C1-C9
3	1	Identify & Stock:  Oty Part Number Description Batch		
		13.7 o  Close W/O  Inspect Level 21	<del>1</del>	04-01-07

BB. 04-01-092B.